


FIG. 1



## FIG. 2




FIG. 3




FIG. 4






FIG. 5

5/16



## FIG. 6



## FIG. 7

```
<startJob>
  <jobConfig>
    <quality>50000000</quality> 700
    <paperSize>51060000</paperSize> 701
    <paperType>52020000</paperType> 702
    <fileType>53000000</fileType> 703
    <datePrint>54010000</datePrint> 704
    <fileNamePrint>55000000</fileNamePrint> 705
    <imageOptimize>56000000</imageOptimize> 706
    <fixedSize>58030000</fixedSize> 707
    <cropping>59000000</cropping> 708
  </jobConfig>
  <printInfo>
    <fileId>00000001</fileId> 709
    <date>2002/10/28</date> 710
  </printInfo>
</startJob>
```

720

721

**FIG. 8A**

prtPID	ImagePath	copyID	progress	Image Printed
--------	-----------	--------	----------	---------------

**FIG. 8B**

dpsPrint ServiceStatus	JobEnd Reason	error Status	error Reason	disconnect Enable	Capability Changed	newJobOK
------------------------	---------------	--------------	--------------	-------------------	--------------------	----------

FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14





FIG. 15



## FIG. 16

